Company:												Date:		
Address: Job Description:					_				Notes: Wall removal					
									New ceramic floor					
CSI Division/Ac	count:							_						
Item or Description	Qty	Unit	Mat Unit \$				Labor MH\$ Ext\$		Equipment Unit \$ Ext \$		Subcontract Unit \$ Ext \$		Total Cost	
Waste Floor					6		\$ 25 /man hr.						\$150	
Prep Floor					2		^{\$} 40						\$ 80	
Refinish Wal	71													
Drywall					1		\$40						\$40	
Paint					2		\$40						\$ 80	
Tile	650 sq'						\$3/sq'						\$1,950	
Grout	650 sq'				2 hours		^{\$} 40						\$80	
Sealer	650 sq'				2		^{\$} 40						\$ 80	
Total Direct Costs this sheet Mater						Total Labor \$		Total Equipment \$		Total Subcontract \$		Total \$		

Todd Hallissey Contracting

Estimate for upper bathroom:

To be removed by owner

- -drywall and tile around tub
- -all existing flooring materials

Remove and dispose by contractor

- -one tub
- vanity
- -toilet to be reinstalled

To be supplied by owner installed by contractor

- -one two-piece shower unit
- -shower faucets
- -vanity with faucets
- -one-piece vinyl flooring
- -all paint done by owner

To be supplied and installed by contractor

- -All ABS fittings and pipe
- -All copper fittings and pipe
- -drywall (dense shield)
- -drywall compound and taping
- -subflooring (1/4" mahogany)

Costs will be for materials and labor \$3172.43

Terms

30% down \$951.73

70% upon completion \$2220.70

Time needed for job - we will require two full weekends,

Starting at 8:00 am finishing at 6:00 pm both Saturdays and Sundays

Start date to be determined between owner and contractor at a later date

Thank you

Todd Hallissey

519-555-0100

